

Inventor(s) : K. MIYANO et al.

Certificate of Correction Branch

Patent No. : 7,062,245

Issued: June 13, 2006

Serial No. : 09/

: 09/739,817

Filed: December 20, 2000

For

: RADIO TRANSMISSION APPARATUS AND RADIO

RECEPTION APPARATUS

COVER LETTER FOR REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
U.S. Patent and Trademark Office
Customer Service Window
Randolph Building
401 Dulany Street
Alexandria, VA 22314

Certificate

SEP 2 6 2006

Of Correction

Sir:

Attached are a Request and a proposed Certificate of Correction in connection with the above-identified patent.

A check in the amount of \$100.00 is enclosed to cover the fee. The Commissioner is hereby authorized to charge any additional fees, or credit any overpayment, to Deposit Account No. 19-0089.

Respectfully submitted,

K. MIYANO et al.

William Pieprz Reg. No. 33630

Bruce H. Bernstein

Reg. No. 29,027

September 21, 2006 GREENBLUM & BERNSTEIN, P.L.C. 1950 Roland Clarke Place Reston, VA 20191 (703) 716-1191

SEP 2 7 2016

SEP. 2 1 2006 IN THE INITED STATES PATENT AND TRADEMARK OFFICE

Inventor(s) : K. MIYANO et al. Certificate of Correction Branch

Patent No. : 7,062,245 Issued: June 13, 2006

Serial No. : 09/739,817 Filed: December 20, 2000

For : RADIO TRANSMISSION APPARATUS AND RADIO

RECEPTION APPARATUS

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
U.S. Patent and Trademark Office
Customer Service Window
Randolph Building
401 Dulany Street
Alexandria, VA 22314

Sir:

Please find attached a proposed Certificate of Correction.

Please correct the following errors appearing in the printed patent which are apparently the fault of the U.S. Patent and Trademark Office, as per the attached Certificate of Correction.

At column 1, line 37 of the printed patent, "Is" should be ---is---. This appeared correctly on page 2, line 11 of the Specification filed December 20, 2000.

At column 1, line 37 of the printed patent, "'0 or 0" should be ---"1 or 0"---. This appeared correctly on page 2, line 12 of the Specification filed December 20, 2000.

At column 5, line 23 of the printed patent, "Is" should be ---is---. This appeared correctly on page 12, line 12 of the Specification filed December 20, 2000.

The following errors are apparently the fault of the Inventor(s):

At column 3, line 16 of the printed patent, "comparing circuit 117" should be --comparing circuit 116---. This appeared incorrectly on page 6, line 19 of the Specification filed
December 20, 2000.

21 FC:1911 123.23 EP

At column 3, line 54 of the printed patent, "polarization antenna 106" should be --polarization antenna 107---. This appeared incorrectly on page 8, line 8 of the Specification filed
December 20, 2000.

At column 6, line 16 of the printed patent, "multiplier 303" should be ---multiplier 301---. This appeared incorrectly on page 14, line 22 of the Specification filed December 20, 2000.

At column 6, line 17 of the printed patent, "transmission signal 303" should be --- transmission signal 302---. This appeared incorrectly on page 14, line 24 of the Specification filed December 20, 2000.

At column 6, line 20 of the printed patent, "transmission signal 303" should be ---transmission signal 302---. This appeared incorrectly on page 14, line 26 of the Specification filed December 20, 2000.

At column 6, line 33 of the printed patent, "D-flip flop" should be ---D-flip flop 401---.

This appeared incorrectly on page 15, line 15 of the Specification filed December 20, 2000.

Therefore, it is respectfully requested that a Certificate of Correction issue in the aboveidentified patent as follows:

At column 1, line 37 of the printed patent, "Is" should be ---is---.

At column 1, line 37 of the printed patent, "'0 or 0'" should be ---"1 or 0"---.

At column 5, line 23 of the printed patent, "Is" should be ---is---.

At column 3, line 16 of the printed patent, "comparing circuit 117" should be --- comparing circuit 116---.

At column 3, line 54 of the printed patent, "polarization antenna 106" should be ---polarization antenna 107---.

At column 6, line 16 of the printed patent, "multiplier 303" should be ---multiplier 301---.

At column 6, line 17 of the printed patent, "transmission signal 303" should be ---transmission signal 302---.

At column 6, line 20 of the printed patent, "transmission signal 303" should be ---transmission signal 302---.

At column 6, line 33 of the printed patent, "D-flip flop" should be ---D-flip flop 401---. Should there be any questions, the Examiner is invited to contact the undersigned at the below-listed number.

Respectfully submitted, K. MIYANO et al.

Bruce H. Bernstein

Reg. No. 29,027

William Pieprz Reg. No. 33630

September 21, 2006 GREENBLUM & BERNSTEIN, P.L.C. 1950 Roland Clarke Place Reston, VA 20191 (703) 716-1191 Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

CERTIFICATE OF CORRECTION		
		Page <u>1</u> of <u>1</u>
PATENT NO. :	: 7,062,245	
APPLICATION NO.:	: 09/739,817	
ISSUE DATE :	: June 13, 2006	
INVENTOR(S) :	K. MIYANO et al.	
	d that an error appears or errors appear in the above-identified patent and the ted as shown below:	at said Letters Patent
At column 1, At column 5, At column 3, At column 3,	1, line 37 of the printed patent, "Is" should beis 1, line 37 of the printed patent, "'0 or 0'" should be"1 or 0" 5, line 23 of the printed patent, "Is" should beis 3, line 16 of the printed patent, "comparing circuit 117" should becomparing, line 54 of the printed patent, "polarization antenna 106" should bepolariz	
At column 6,	6, line 16 of the printed patent, "multiplier 303" should bemultiplier 301 5, line 17 of the printed patent, "transmission signal 303" should betransm	ission signal
	6, line 20 of the printed patent, "transmission signal 303" should betransm	ission signal
302 At column 6,	6, line 33 of the printed patent, "D-flip flop" should beD-flip flop 401	

MAILING ADDRESS OF SENDER (Please do not use customer number below):

GREENBLUM & BERNSTEIN, P.L.C. 1950 Roland Clarke Place Reston, VA 20191

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

MAILING ADDRESS OF SENDER (Please do not use customer number below):

GREENBLUM & BERNSTEIN, P.L.C. 1950 Roland Clarke Place Reston, VA 20191

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.